

ALASKA DEPARTMENT OF ENVIRONMENTAL CONSERVATION
Division of Spill Prevention and Response
Prevention and Emergency Response Program

SITUATION REPORT

INCIDENT NAME: F/V Nahanni Sinking

SITREP #: 2 and Final

SPILL NUMBER: 09229923401

LEDGER CODE: not requested

TIME/DATE OF SPILL: 8:30 PM, August 22, 2009

TIME/DATE OF SITUATION REPORT: 2:00 PM, September 23, 2010

TIME/DATE OF THE NEXT REPORT: This is the final situation report for this incident.

TYPE/AMOUNT OF PRODUCT SPILLED: There is a potential spill of 300 gallons of diesel and 40 gallons of lubricating oil. As of this report only light sheens have been reported.

LOCATION: Elrington Passage at Evans Island in Prince William Sound. The location is just outside of Sawmill Bay to the south west at a Lat/Lon of 60° 02.56'N, 148° 02.06'W

CAUSE OF SPILL: On August 22, the vessel struck a reef and began taking on water after delivering a load of fish.

POTENTIAL RESPONSIBLE PARTY (PRP): Ryan Rogers

RESPONSE ACTION: Good Samaritan vessels in the vicinity assisted in rescuing the crew and placing boom provided by the nearby hatchery. Pumps were unable to keep up with the in-flowing water and the vessel eventually rolled over with the stern up and the bow down. During the night on August 23, the vessel completely sank in an estimated 90 feet of water as determined by the still attached boom.

Alaska Chadux and Storm Chasers Marine Services, Incorporated were contracted by the PRP to assess and attempt to recover the vessel. Both had additional spill response and lightering equipment on-scene to prevent any further potential pollution impacts near Sawmill Bay.

The F/V Nahanni was raised from nearly 100 feet of water using inflatable lift bags by Storm Chasers Marine Services, Inc. The vessel was then moved to a nearby beach and grounded so that repairs could be made and the vessel was lightered and made sea-worthy for a tow to Seward. After a safe journey to Seward the vessel was removed from the water to dry dock.

SOURCE CONTROL: The vents on the fuel tanks were sealed by the crew before they abandoned the vessel. These seals held and only minor residual amounts of sheen were released within the containment boom.

RESOURCES AFFECTED: No waterfowl, otters or other resources were reported as having been impacted. Also, the Hatchery at the head of Sawmill Bay was not impacted.

FUTURE PLANS AND RECOMMENDATIONS: The vessel remains in dry dock.

WEATHER: Weather during the recovery and salvage operations were generally favorable

UNIFIED COMMAND AND PERSONNEL:

Incident Commander: Ryan Rogers
F.O.S.C.: CDR Darryl Verfaillie, USCG, Valdez
S.O.S.C.: Gary Folley, ADEC

FOR ADDITIONAL INFORMATION CONTACT: John W. Engles, ADEC Valdez (907) 835-4698

AGENCY/STAKEHOLDER NOTIFICATION LIST

This sitrep has been distributed via email to the Governor's office, ADF&G, ADNR, SECC, USEPA, USDOJ, NMFS, USFWS, and USFS in addition to the following.

AGENCY	NAME	Sent Via		Telephone	Facsimile
USCG-MSO/Valdez	CDR. Valdez-office	Fax		835-7210	835-7207
US EPA	Matt Carr	Fax		271-5083	271-3424
USDA Forest Service	Ken Vaughan Deputy Director of Engineering and Aviation Management	Email/fax	KVaughan@fs.fed.us	586-8789	586-7555
USDA Forest Service	Gerry Xavier Engineering Staff Officer, Chugach National Forest	Email/fax	GXavier@fs.fed.us	743-9544	743-9476
OTHER					
PWS/RCAC	John Devens	Fax		277-7222	277-4523
CIRCAC	Mike Munger	Fax/Email	munger@circac.org	283-7222	283-6102
Mayor of Cordova	Mayor's Office	Fax		424-6200	424-6000
Mayor of Valdez	Mayor's Office	Fax		835-4313	835-2992
			Session/Interim		
Senate F/ Fairbanks	Gene Therriault	Fax	Juneau 5/16 - 1/09 Juneau 1/10 - 5/15	465-4797 465-4797	465-3884 465-3884
House 35/Valdez	John Harris	Fax	Juneau 5/16 - 1/09 Juneau 1/10 - 5/15	465-4859 465-4859	465-3799 465-3799



F/V Nahanni being raised



F/V Nahanni grounded on beach for repairs

These three photos are
courtesy of Alaska Marine
Surveyors, Inc.



F/V Nahanni coming out of the water at Storm Chasers facility in Seward